2015.8.4

Overview：

1. All-in-One firmware version updated to：v1.3.20
2. DJI GO app iOS version updated to: v2.0.0

What's New：

1. Added HD Video Conversion option in the video editor when cutting footage to video.
2. Automatic photo syncing of the compressed files to your mobile device.
3. Added option to downgrade the aircraft firmware (remote controller version will be released soon).

Bug Fixes：

1. Fixed issue of the camera failing to save photos when shooting in burst mode.

Notice：

- The firmware can be downgraded to v1.1.9 or later only.

2015.6.15

Overview：

1. All-in-One Firmware version updated to：v1.2.6

Major Updates：

1. Anti-distortion feature added for images and non-4K videos.
2. Various bug fixes.

2015.5.22

Overview：

1. All-in-One Firmware version updated to：v1.1.9

Major Updates：

1. Fixed issue of some aircraft unable to determine their altitudes.
2. Fixed issue of the DJI Pilot app unable to obtain and display battery error history.
3. Fixed issue of the compass calibration progress not being displayed properly.

Notice：

● Users are advised to update the firmware version to v1.1.9, otherwise future firmware will not be able to install.
● Users may skip updating the remote controller if they have already updated the firmware to v1.1.8, as the latest firmware update does not affect the remote controller.

2015.5.8

Overview：

2. All-in-One Firmware version updated to：v1.1.8

Major Updates：

1. Fixed the issue of failure to update the firmware if the remote controller is turned off.

Notice：

● Users are advised to update the firmware version to v1.1.8, otherwise future firmware will not be able to install.
● Re-link the remote controller to the aircraft if the connection is lost after the firmware update.

2015.5.6

Overview：

1. All-in-One Firmware version updated to：v1.1.6
2. DJI Pilot app iOS version updated to: v1.1.1
3. DJI Pilot app Android version updated to: v1.1.0

Major Updates：

Updated to be compatible with the iOS version of the DJI Pilot app.

Notice：

Re-link the remote controller to the aircraft if the connection is lost after the firmware upgrade.