2015.9.7

Overview:

1. All-in-one firmware version updated to: v1.4.0010

2. DJI GO app iOS version updated to: v2.2.0

3. DJI GO app Android version updated to: v2.1.0

What's New:

- 1. Added Intelligent Navigation Modes including Point of Interest, Follow Me and Waypoint.
- 2. The Phantom 3 Advanced now supports 2.7K (2704x1520p30) video recording.
- 3. The photo format now cannot be changed when the camera is in operation.

Bug Fixes:

1. Removed the vision position system altitude record from the video caption.

Notice:

- Users may skip updating the remote controller, as the latest firmware update does not affect the remote controller
- It is normal for the motor to sound or the LED to blink during the update process, as the latest firmware update will affect the motor.

2015.8.4

Overview:

- 1. All-in-one firmware version updated to: v1.3.20
- 2. DJI GO app iOS version updated to: v2.0.0
- 3. DJI GO app Android version updated to: v2.0.0

What's New:

- 1. Added HD Video Conversion option in the video editor when cutting footage to video.
- 2. Automatic photo syncing of the compressed file to your mobile device.
- 3. Added option to downgrade the aircraft firmware (remote controller version will be released soon).
- 4. Camera View now displays the DJI logo if a video output error is detected to avoid confusion with a blank screen.

Bug Fixes:

- 1. Fixed issue of the camera failing to save photos when shooting in burst mode.
- 2. Fixed issue of Camera View occasionally displaying a blank screen while recording video.

Notice:

• The firmware can be downgraded to v1.1.9 or later only.

2015.6.18

Overview:

4. All-in-One Firmware version updated to: v1.2.8

Major Updates:

1. Fixed issue of unwanted lines at the bottom of photos and videos when the image scale is set to 4:3.

Notice:

• Users may skip updating the remote controller if they have already updated the firmware to v1.2.7, as the latest firmware update does not affect the remote controller.

2015.6.15

Overview:

5. All-in-One Firmware version updated to: v1.2.7

Major Updates:

- 3. Anti-distortion feature added for images and non-4K videos.
- 4. Various bug fixes.

2015.5.22

Overview:

1. All-in-One Firmware version updated to: v1.1.9

Major Updates:

- 1. Fixed issue of some aircraft unable to determine their altitudes.
- 2. Fixed issue of the DJI Pilot app unable to obtain and display battery error history.
- 3. Fixed issue of the compass calibration progress not being displayed properly.

Notice:

- Users are advised to update the firmware version to v1.1.9, otherwise future firmware will not be able to install.
- Users may skip updating the remote controller if they have already updated the firmware to vl.l.8, as the latest firmware update does not affect the remote controller.

2015.5.8

Overview:

1. All-in-One Firmware version updated to: v1.1.8

Major Updates:

1. Fixed the issue of failure to update the firmware if the remote controller is turned off.

Notice:

- Users are advised to update the firmware version to v1.1.8, otherwise future firmware will not be able to install.
- Re-link the remote controller to the aircraft if the connection is lost after the firmware update.

2015.5.6

Overview:

- 1. All-in-One Firmware version updated to: v1.1.6
- 2. DJI Pilot app iOS version updated to: vl.1.1
- 3. DJI Pilot app Android version updated to: v1.1.0

Major Updates:

1. Updated to be compatible with the iOS version of the DJI Pilot app.

Notice:

Re-link the remote controller to the aircraft if the connection is lost after the firmware upgrade.